

WAGE AND LABOR STANDARDS ADMINISTRATION
Bureau of Labor Standards

DPM 968

MATERIAL SAFETY DATA SHEET

SECTION I

MANUFACTURER'S NAME Allied-Kelite Products		EMERGENCY TELEPHONE NO. (213) 222-0201
ADDRESS (Number, Street, City, State, and ZIP Code) 1250 N. Main St., Los Angeles, Calif. 90012		
CHEMICAL NAME AND SYNONYMS Not applicable		TRADE NAME AND SYNONYMS Deseal A
CHEMICAL FAMILY Not applicable	FORMULA Blend	

SECTION II HAZARDOUS INGREDIENTS

PAINTS, PRESERVATIVES, & SOLVENTS	%	TLV (Units)	ALLOYS AND METALLIC COATINGS	%	TLV (Units)
PIGMENTS	0		BASE METAL	0	
CATALYST	0		ALLOYS	0	
VEHICLE	0		METALLIC COATINGS	0	
SOLVENTS Methylene chloride-over	50%		FILLER METAL PLUS COATING OR CORE FLUX	0	
ADDITIVES	0		OTHERS	0	
OTHERS	0				
HAZARDOUS MIXTURES OF OTHER LIQUIDS, SOLIDS, OR GASES				%	TLV (Units)
Mercaptans				Less than	5%

SECTION III PHYSICAL DATA

BOILING POINT (°F.)	95-100° F	SPECIFIC GRAVITY (H ₂ O=1)	Approx	1.25
VAPOR PRESSURE (mm Hg.)	Unknown	PERCENT VOLATILE BY VOLUME (%)	Over	80%
VAPOR DENSITY (AIR=1)	Unknown	EVAPORATION RATE (_____ =1)		Unknown
SOLUBILITY IN WATER	Not soluble			
APPEARANCE AND ODOR	Liquid - mercaptan odor			

SECTION IV FIRE AND EXPLOSION HAZARD DATA

FLASH POINT (Method used) None	FLAMMABLE LIMITS Not flammable	Lel	Uel
EXTINGUISHING MEDIA Material will not support combustion			
SPECIAL FIRE FIGHTING PROCEDURES			
UNUSUAL FIRE AND EXPLOSION HAZARDS Direct contact with flames may produce phosgene			

SECTION V HEALTH HAZARD DATA

THRESHOLD LIMIT VALUE

Unknown

EFFECTS OF OVEREXPOSURE

Prolonged inhalation of vapors may cause irritation to eyes and respiratory tract.

EMERGENCY AND FIRST AID PROCEDURES

EXTERNAL: Wash with soap and water.

INTERNAL: Emetic to produce vomiting. Obtain medical attention.

EYES: Flush with large amounts of water. Obtain medical attention.

SECTION VI REACTIVITY DATA

STABILITY

UNSTABLE

CONDITIONS TO AVOID

STABLE

XX

INCOMPATIBILITY (Materials to avoid)

Avoid contact with strong oxidizers.

HAZARDOUS DECOMPOSITION PRODUCTS

Phosgene may be produced upon direct contact with open flames.

HAZARDOUS
POLYMERIZATION

MAY OCCUR

CONDITIONS TO AVOID

WILL NOT OCCUR

XX

SECTION VII SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED

Flush area with water.

WASTE DISPOSAL METHOD

Truck out.

SECTION VIII SPECIAL PROTECTION INFORMATION

RESPIRATORY PROTECTION (Specify type)

VENTILATION

LOCAL EXHAUST XXX

SPECIAL

MECHANICAL (General)

OTHER

PROTECTIVE GLOVES

Yes

EYE PROTECTION

Yes

OTHER PROTECTIVE EQUIPMENT

Aprons

SECTION IX SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING

Do not store in sunlight or at elevated temperatures.

OTHER PRECAUTIONS

Avoid contact with skin, eyes and clothing.